

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026409**Date Inspected:** 05-Sep-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1200**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2200**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island**Location:** Shanghai, China

CWI Name: Guo Xing Hui

Inspected CWI report:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A

CWI Present:	Yes	No
Rod Oven in Use:	Yes	No
Weld Procedures Followed:	Yes	No
Verified Joint Fit-up:	Yes	No
Approved WPS:	Yes	No
Delayed / Cancelled:	Yes	No

Bridge No: 34-0006**Component:** Bike Path, Traveler Rail**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dennis Combs, was present during the times noted above for the observations relative to the work being performed.

Bay 19

This QA Inspector observed the fit up of CJP weld joints located on Bike Path segment BK9003. Verified the fit up of the following CJP weld joints BK9003A2-001-065~068, and BK9003A2-001-069~072, these joints appear to conform to the requirements of the approved contract documents. Tack welding of these joints was performed by certified welder 062749. QC Guo Xing Hui present during welding.

Bay 9

This QA Inspector observed the following work in progress for Bay 9.

ZPMC was using the Flux Cored Arc Welding(FCAW) process.

ZPMC QC is identified as Zhu Zhung Jie.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Component: Traveler Rail

PCMK: 3018TR1

WELDING INSPECTION REPORT



(Continued Page 2 of 2)

Weld Number: 032, 033

Welder: 059443

WPS-B-T-2232-ESAB

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By: Combs,Dennis

Quality Assurance Inspector

Reviewed By: Riley,Ken

QA Reviewer